

Fig. 1

BEST AVAILABLE COPY





Fig. 2






Foam Fractionator - O3 flows of 30-50 % of total requirement allowable. Minimal residual ozone will not significantly impact biofilter

LHO - O3 flows of 50-100 % of total requirement allowable. Ozone destruct to O2 provide additional O2 flow through LHO.

FIG. 3


Copyright 2001 ©
 Water Management Technologies, Inc.
 All rights Reserved, Water Management Technologies, Inc.
 Reprinting, reproduction or redistribution by permission only.

| | | |
|-------------------------------------|--|--------------|
| Water Management Technologies, Inc. | Drawing: Integrated Modular Filtration System - Process Flow Diagram | Revision: 0 |
| Date: 10/21/02 | Drawn By: Greg Beckman | Sheet 1 of 1 |




FRP - FRP Flange Connection System

FIG. 4





5A



5B

FRP - Concrete Connection Method

FIG 5





Slot Attachment Method

FIG. 6


FIG. 7

CO₂ Stripper Module






8A






8B




8C

Foam Fractionation - Base Module & Insert
FIG. 8



Biofilter Module(s)

F16.9



Ultra-violet Light & Low Head Oxygenator (LHO) Module

FIG. 10




Fig. 11

**This Page is Inserted by IFW Indexing and Scanning
Operations and is not part of the Official Record**

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

☐ BLACK BORDERS

☐ IMAGE CUT OFF AT TOP, BOTTOM OR SIDES

☐ FADED TEXT OR DRAWING

☒ BLURRED OR ILLEGIBLE TEXT OR DRAWING

☐ SKEWED/SLANTED IMAGES

☒ COLOR OR BLACK AND WHITE PHOTOGRAPHS

☐ GRAY SCALE DOCUMENTS

☐ LINES OR MARKS ON ORIGINAL DOCUMENT

☐ REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY

☐ OTHER: _____

IMAGES ARE BEST AVAILABLE COPY.

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.